



Supistusyhde, malli 3242



Supistusyhde, malli 3242



$\frac{1}{8} \times \frac{1}{4}$



Supistus, malli 3242

441 128



$\frac{1}{8} \times \frac{3}{8}$



Supistus, malli 3242

441 135



$\frac{1}{4} \times \frac{3}{8}$



Supistus, malli 3242

322 540



$\frac{3}{8} \times \frac{1}{2}$



Supistusyhde, malli 3242

322 564



$\frac{3}{8} \times \frac{3}{4}$



Supistusyhde, malli 3242

322 557



$\frac{1}{2} \times \frac{3}{8}$



Supistusyhde, malli 3242

319 083



$\frac{1}{2} \times \frac{3}{4}$



Supistus, malli 3242

320 423



$\frac{1}{2} \times 1$



Supistusyhde, malli 3242

320 430



$\frac{1}{2} \times 1\frac{1}{4}$



Supistusyhde, malli 3242

650 889



$\frac{3}{4} \times \frac{1}{2}$



Supistus, malli 3242

441 142



$\frac{3}{4} \times 1$

335 311

$\frac{3}{4} \times 1\frac{1}{4}$

441 357



Supistus, malli 3242



Supistusyhde, malli 3242



$\frac{3}{4} \times 1\frac{1}{2}$



Supistus, malli 3242

650 841

$1 \times 1\frac{1}{4}$



Supistus, malli 3242

359 348



$1 \times 1\frac{1}{2}$



Supistus, malli 3242

650 858

1×2



650 872

$1\frac{1}{4} \times 1\frac{1}{2}$

650 865