




T-yhde, malli 3130



T-yhde, malli 3130



Rp1	Rp2	Rp3
$\frac{1}{8}$	$\frac{1}{8}$	$\frac{1}{8}$

441 081

Rp1	Rp2	Rp3
$\frac{1}{4}$	$\frac{1}{4}$	$\frac{1}{4}$


318 017



T-yhde, malli 3130



T-yhde, malli 3130



Rp1	Rp2	Rp3
$\frac{3}{8}$	$\frac{3}{8}$	$\frac{3}{8}$


281 809

Rp2


264 222



T-yhde, malli 3130



T-yhde, malli 3130



$\frac{1}{2} \times \frac{3}{8} \times \frac{1}{2}$

264 444

Rp2


264 246



T-yhde, malli 3130



T-yhde, malli 3130



$\frac{3}{4} \times \frac{1}{2} \times \frac{1}{2}$

362 492

$\frac{3}{4} \times \frac{1}{2} \times \frac{3}{4}$


264 468



T-yhde, malli 3130



T-yhde, malli 3130



$\frac{3}{4} \times \frac{3}{4} \times \frac{1}{2}$

362 508

Rp2


264 260



T-yhde, malli 3130



T-yhde, malli 3130



1 x ½ x 1

362 515

1 x ¾ x 1

264 420



T-yhde, malli 3130



T-yhde, malli 3130



1 x 1 x ½

362 522

1¼


264 284



T-yhde, malli 3130



T-yhde, malli 3130



1¼ x ½ x 1¼

650 735

1¼ x ¾ x 1¼

650 742



T-yhde, malli 3130



T-yhde, malli 3130



1½

264 307

1½ x ½ x 1½

650 759



T-yhde, malli 3130



T-yhde, malli 3130



1½ x ¾ x 1½

650 766

Rp1	Rp2	Rp3
2	2	2

264 321

viega



4 015211 650773

T-yhde, malli 3130



viega



4 015211 321734

T-yhde, malli 3130



2 x 1 x 2

650 773

2½

321 734

viega



4 015211 321727

T-yhde, malli 3130



Rp1	Rp2	Rp3
3	3	3

321 727