

viega



4 015211 441081

T-yhde, malli 3130




viega



4 015211 318017

T-yhde, malli 3130



Rp1	Rp2	Rp3
1/8	1/8	1/8

441 081

Rp1	Rp2	Rp3
1/4	1/4	1/4

318 017

viega



4 015211 281809

T-yhde, malli 3130




viega



4 015211 264222

T-yhde, malli 3130



Rp1	Rp2	Rp3
3/8	3/8	3/8

281 809

Rp1	Rp2	Rp3
1/2	1/2	1/2


264 222

viega



4 015211 264444

T-yhde, malli 3130




viega



4 015211 264246

T-yhde, malli 3130



$\frac{1}{2} \times \frac{3}{8} \times \frac{1}{2}$

264 444

Rp1	Rp2	Rp3
3/4	3/4	3/4

264 246

viega



4 015211 362492

T-yhde, malli 3130




viega



4 015211 264468

T-yhde, malli 3130



$\frac{3}{4} \times \frac{1}{2} \times \frac{1}{2}$

362 492

$\frac{3}{4} \times \frac{1}{2} \times \frac{3}{4}$

264 468

viega



4 015211 362508

T-yhde, malli 3130



viega



4 015211 264260

T-yhde, malli 3130



$\frac{3}{4} \times \frac{3}{4} \times \frac{1}{2}$

362 508

Rp1	Rp2	Rp3
1	1	1

264 260

viega



4 015211 362515

T-yhde, malli 3130




viega



4 015211 264420

T-yhde, malli 3130



$1 \times \frac{1}{2} \times 1$

362 515

$1 \times \frac{3}{4} \times 1$

264 420

viega



T-yhde, malli 3130

1 x 1 x 1/2

viega



T-yhde, malli 3130

1 1/4 x 1/2 x 1 1/4

viega



T-yhde, malli 3130

1 1/2

viega



T-yhde, malli 3130

1 1/2 x 3/4 x 1 1/2

viega



T-yhde, malli 3130

2 x 1 x 2

viega



T-yhde, malli 3130

Rp1	Rp2	Rp3
3	3	3



viega



T-yhde, malli 3130

362 522

1 1/4



viega



T-yhde, malli 3130

650 735

1 1/4 x 3/4 x 1 1/4



viega



T-yhde, malli 3130

264 307

1 1/2 x 1/2 x 1 1/2



viega



T-yhde, malli 3130

650 766

Rp1	Rp2	Rp3
2	2	2



viega



T-yhde, malli 3130

650 773

2 1/2



321 727



264 284



650 742



650 759



264 321



321 734